

Task Risk Control Sheet

Lead Work

RCS No: NR/L3/MTC/RCS0216/PR07
Issue: 2

	<ul style="list-style-type: none"> Lead Poisoning Back Injury Burns 	Personnel Involved	E&P	
			S&T	
			Track	
			Off Track	
			Property	✓

Tools / Equipment	Hand Tools	Scaffold	Power Tools
Plant			

Task Risks	Controls	Implemented By
Lead Poisoning	<ul style="list-style-type: none"> A competent person shall be employed to assess whether or not the <u>degree of exposure to lead is significant</u>. 	Line Manager
	<ul style="list-style-type: none"> Appropriate PPE shall be worn if exposure risk is significant. 	Staff
	<ul style="list-style-type: none"> Eating, Drinking and Smoking is prohibited in areas, which are <u>likely to be contaminated by lead</u>. 	Staff
	<ul style="list-style-type: none"> Adequate washing and changing facilities shall be provided and <u>used by workers so personal hygiene standards</u>. 	Line Manager / Staff
	<ul style="list-style-type: none"> Workers shall wash their hands and arms thoroughly before eating and drinking at the end of the day; particular attention shall be given to scrubbing under the nails to remove traces of <u>lead</u>. 	Staff
Back Injury	<ul style="list-style-type: none"> Medical surveillance shall be carried out if exposure is significant. 	Line Manager
	<ul style="list-style-type: none"> Where large pieces of lead are to be carried, assistance shall be sought - mechanical handling devices shall be used where practicable, and where lead is to be carried out onto roofs, suitable lifting devices shall be provided. 	Line Manager / Staff
Burns	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GH01 – Manual Handling 	Line Manager / Staff
Work at Height	<ul style="list-style-type: none"> Appropriate PPE shall be worn. 	Line Manager / Staff
	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GH04 – Working at Height. 	

Task Risk Control Sheet

PPE Required by NR / Maintenance Policy



Wear Head Protection



Wear Foot Protection



Wear Hi Visibility Clothing



Wear Safety glasses to BS EN 166.F

If safety glasses introduce a risk (ie weather conditions) then the Team Leader shall assess the risk. The outcome of the assessment shall be recorded on the SSOWPS pack and safety glasses may be removed.

This does not supersede the requirements for eye protection detailed on relevant Task Risk Control Sheets.

Additional PPE Required by Task Risk Control Sheet



Wear Hand Protection



Wear goggles/face visor to BS EN 166.B



Wear Respiratory Protection



Wear Safety Harness