Task Risk Control Sheet

Repairing and Jointing Cables

RCS No: NR/L3/MTC/RCS0216/SIG13
Issue: 2

Key Risks !

- **Electrical Hazard**
- **Vermin Contamination**
- **Needle/Sharps stick injury**

Personnel Involved		
	E&P	
	S&T	✓
	P/Way	
	Off Track	
	Property	

Tools / Equipment Various Hand Tools

Plant

Key Risks	Controls	Implemented By
General Hazards	• Set up a safe system of work	COSS
	• See Risk control Sheet NR/L3/MTC/RCS0216/GA01 – Work On or Near The Line • See Risk control Sheet NR/L3/MTC/RCS0216/GH02 – Underfoot Conditions • See Risk control Sheet NR/L3/MTC/RCS0216/GH01 – Manual Handling • See Risk control Sheet NR/L3/MTC/RCS0216/GH03 – Biological and Chemical Hazards	Team Leader / All Staff
Electrocution	• See Risk Control sheets NR/L3/MTC/RCS0216/GA20 Working Adjacent to DC Electrified Rails Risk Level 1- 5, • See Risk Control Sheet NR/L3/MTC/RCS0216/GA21 - Working Near Electrical Overhead Line Equipment • You and any tools or equipment you are carrying/using, shall be at least 2.75m (9 Feet) from the OLE unless an isolation has been arranged and a form C has been issued and available on site with the nominated competent COSS • Or you are working within the confines of a cage or suitable protection arrangements.	Team Leader/ COSS/ All Staff
Electrical Hazard	• Isolate equipment if practical	Team Leader
	• Use insulated tools as required. • PPE shall be worn in accordance with SPWEE or EAW 1, 2, or 3.	All Staff
Vermin Vegetation and Weed contamination	• Hand protection. • Suitable hand cleaner /washing facilities shall be available	Team Leader / All Staff
Needle / Sharps stick injury	• Be vigilant when conducting work. • See Risk control Sheet NR/L3/MTC/RCS0216/GA22 -Removal of discarded needles and syringes.	All Staff

Copyright Network Rail
Provided by IHS under license with Network Rail
No reproduction or networking permitted without license from IHS
Full document details: NR NR-L3-MTC-RCS0216-SIG13 I 2012
Licensee=Weston Williamson/5989497001, User=sam, albett
Not for Resale, 03/27/2016 20:04:22 MDT
Documents
Document Sharing Hub

Task Risk Control Sheet

Network Rail

PPE Required by NR / Maintenance Policy				
Wear Head Protection	Wear Foot Protection	Wear Hi Visibility Clothing	Wear Safety glasses to BS EN166.F	**If safety glasses introduce a risk (ie weather conditions) then the Team Leader shall assess the risk. The outcome of the assessment shall be recorded on the SSOWPS pack and safety glasses may be removed. This does not supersede the requirements for eye protection detailed on relevant Task Risk Control Sheets.**

Additional PPE Required by Task Risk Control Sheet						
Wear Hand Protection						

Copyright Network Rail
Provided by IHS under license with Network Rail
No reproduction or networking permitted without license from IHS
Full document details: NR NR-L3-MTC-RCS0216-SIG13 I 2012
Licensee=Weston Williamson/5989497001, User=sam, albett
Not for Resale, 03/27/2016 20:04:22 MDT
AVA Documents
Document Sharing Hub