

Task Risk Control Sheet

Station Information & Security Systems (SISS) and DOO Systems

RCS No: NR/L3/MTC/RCS0216/TEL12
Issue: 2

	Public Areas	Personnel Involved	E&P	
	Electrical Hazards		S&T	✓
	Working on Station Platforms		Track	
	CRT Monitors		Off Track	
	LCD / Plasma / TFT Screens		Property	

Tools / Equipment	Hand Tools	Electronic Meters	Ladders
	Lifting Equipment		
Plant	Cherry Pickers	Mobile Platform	

Task Risks	Controls	Implemented By
Generic Risks	<ul style="list-style-type: none"> Refer to RCS Manual section GA,GH and GHE for generic risks associated with working on the railway, MP for mobile plant and SP for use of small plant. 	Team Leader
Public Areas	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GA04 - Working In or Near Public Areas 	Team Leader / All Staff
Electrical Hazards	<ul style="list-style-type: none"> Be aware of high voltage cables and take care not to damage Be aware of exposed power terminals Be aware of high voltages within monitors 	Team Leader / All Staff
Working on Station Platforms	<ul style="list-style-type: none"> Use barriers around work site 	Team Leader / All Staff
CRT Monitors	<ul style="list-style-type: none"> High voltages – discharge where appropriate using Discharge Probe Avoid breaking neck or puncturing when transporting or fitting. Use appropriate storage boxes 	Team Leader / All Staff
LCD / Plasma / TFT Screens	<ul style="list-style-type: none"> Avoid puncturing when transporting or fitting. Use appropriate storage boxes 	Team Leader / All Staff
Working at Heights	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GH04 Working at Height 	Team Leader / All Staff
Heated Mirrors	<ul style="list-style-type: none"> Do not touch heating element 	Team Leader / All Staff
OLE Equipment	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GA21– Work near overhead line equipment 	Team Leader / All Staff

Task Risk Control Sheet

PPE Required by NR / Maintenance Policy



Wear Head Protection



Wear Foot Protection



Wear Hi Visibility Clothing



Wear Safety glasses to BS EN166.F

If safety glasses introduce a risk (ie weather conditions) then the Team Leader shall assess the risk. The outcome of the assessment shall be recorded on the SSOWPS pack and safety glasses may be removed.

This does not supersede the requirements for eye protection detailed on relevant Task Risk Control Sheets.

Additional PPE Required by Task Risk Control Sheet



Wear Hand Protection



Wear Safety Harness

Copyright Network Rail