

Installation Engineer Briefing Note

For approval and authorisation of this document, please refer to the IECC Applications Manual Contents, RT/E/S/10040.

This document is the property of Network Rail. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the document owner.

**Published and issued by
Network Rail
40 Melton Street
LONDON
NW1 2EE**

© 2004 Network Rail

This page is intentionally blank

Amendment Record

Issue	Date	Description
1	15 April 2003	Initial issue.
2	3 June 2003	Section 2.1 typographical correction. Section 2.2 amended in accordance with System Support Request D335. Section 3.1 amended in accordance with System Support Requests D336, D337 and D338.
3	29 August 2003	Section 2.2 updated as follows as a result of the IECC Upgrade 003 Pilot Installation Critical Review Report (SCS-SSP(003)-SA-18): Amended to state that spare keyboards need to be updated with new keys. Amended to state that the audible SPAD alarm must be tested on both DIS computer units on all workstations. Amended to include documents and drawings to be supplied to site.
4	29 January 2004	Sections 2.2 and 4 amended for conversion of PSM to IPL.

Author	Approved	Date	Authorised	Date
--------	----------	------	------------	------

IECC BRIEFING NOTE
IECC UPGRADE 003 INSTALLATION ENGINEER BRIEFING NOTE

SCS-SSP(003)-UG-4 Issue 4

Document Details: SCS-SSP(003)-UG-4 ISSUE 4 2004