

Railway Group Standard

GE/RT8034

Issue Two

Date September 2013

Maintenance of Signal and Operational Sign Visibility

Synopsis

This document mandates the requirements necessary to ensure that the visibility and alignment of signals, and operational signs that perform the function of signals, are not adversely affected during the life of the equipment.

Copyright in the Railway Group Standards is owned by Rail Safety and Standards Board Limited. All rights are hereby reserved. No Railway Group Standard (in whole or in part) may be reproduced, stored in a retrieval system, or transmitted, in any form or means, without the prior written permission of Rail Safety and Standards Board Limited, or as expressly permitted by law.

RSSB Members are granted copyright licence in accordance with the Constitution Agreement relating to Rail Safety and Standards Board Limited.

In circumstances where Rail Safety and Standards Board Limited has granted a particular person or organisation permission to copy extracts from Railway Group Standards, Rail Safety and Standards Board Limited accepts no responsibility for, nor any liability in connection with, the use of such extracts, or any claims arising therefrom. This disclaimer applies to all forms of media in which extracts from Railway Group Standards may be reproduced.

Published by:

**RSSB
Block 2
Angel Square
1 Torrens Street
London
EC1V 1NY**

**© Copyright 2013
Rail Safety and Standards Board Limited**

Railway Group Standard

GE/RT8034

Issue Two

Date September 2013

Maintenance of Signal and Operational Sign Visibility

Issue record

Issue	Date	Comments
One	December 2001	Original document
Two	September 2013	Replaces issue one. A number of clauses have been withdrawn because: a) They are not true measures and do not comply with the criteria in Part 4 of the RGS Code, section 4.2.1. b) They are the responsibility of a single duty holder and so do not comply with the criteria in Part 4 of the RGS Code, section 4.2.1. c) Their effects are duplicated by measures in other RGSs and are therefore redundant.

Revisions have not been marked by a vertical black line in this issue because the document has been revised throughout.

Superseded documents

The following Railway Group Standard is superseded, either in whole or in part as indicated:

Superseded documents	Sections superseded	Date when sections are superseded
GE/RT8034 issue one Maintenance of Signal Visibility	All	07 December 2013

GE/RT8034 issue one Maintenance of Signal Visibility, ceases to be in force and is withdrawn as of 07 December 2013.

Supply

The authoritative version of this document is available at www.rgsonline.co.uk.
Uncontrolled copies of this document can be obtained from Communications, RSSB, Block 2, Angel Square, 1 Torrens Street, London EC1V 1NY, telephone 020 3142 5400 or e-mail enquirydesk@rssb.co.uk. Other Standards and associated documents can also be viewed at www.rgsonline.co.uk.

Maintenance of Signal and Operational Sign Visibility

Contents

Section	Description	Page
Part 1	Purpose and Introduction	4
1.1	Purpose	4
1.2	Introduction	4
1.3	Approval and authorisation of this document	4
Part 2	Requirements for Maintenance of Signal and Operational Sign Visibility	5
2.1	Introduction	5
2.2	Reporting and assessment process	5
2.3	Signal or operational sign found to have a sighting defect	6
Part 3	Application of this Document	7
3.1	Application - infrastructure managers	7
3.2	Application - railway undertakings	7
3.3	Health and safety responsibilities	8
Definitions and Abbreviations		9
References		10