

H-35-19



AEROSPACE RECOMMENDED PRACTICE

Society of Automotive Engineers, Inc.

TWO PENNSYLVANIA PLAZA, NEW YORK, N. Y. 10001

ARP 590 B

Issued 11-15-59

Revised 12-15-71

SPARK PLUG, AIRCRAFT RECIPROCATING ENGINE




FIG. 1




FIG. 2




FIG. 3

SECTION "AA" ENLARGED




FIG. 4

SECTION "AA" ENLARGED

SAE Technical Board rules provide that: "All technical reports, including standards approved and practices recommended, are advisory only. Their use by anyone engaged in industry or trade is entirely voluntary. There is no agreement to adhere to any SAE standard or recommended practice, and no commitment to conform to or be guided by any technical report. In formulating and approving technical reports, the Board and its Committees will not investigate or consider patents which may apply to the subject matter. Prospective users of the report are responsible for protecting themselves against liability for infringement of patents."



Documents

Document Sharing Hub

PROBLEM HARD COPY

