



AEROSPACE STANDARD

AS4156™**REV. D**

Issued	1989-10
Revised	2014-07
Reaffirmed	2020-03
Stabilized	2025-12

Superseding AS4156C

Color-Coded Incandescent Flange Base T-1 and T-1 3/4 Lamps for Voltage Identification

RATIONALE

The technical report covers technology, products, or processes which are mature and not likely to change in the foreseeable future.

STABILIZED NOTICE

This document has been declared "STABILIZED" by SAE A-20A Crew Station Lighting Committee and will no longer be subjected to periodic reviews for currency. Users are responsible for verifying references and continued suitability of technical requirements. Newer technology may exist.

SAE Executive Standards Committee Rules provide that: "This report is published by SAE to advance the state of technical and engineering sciences. The use of this report is entirely voluntary, and its applicability and suitability for any particular use, including any patent infringement arising therefrom, is the sole responsibility of the user."

SAE reviews each technical report at least every five years at which time it may be revised, reaffirmed, stabilized, or cancelled. SAE invites your written comments and suggestions.

Copyright © 2025 SAE International

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, or used for text and data mining, AI training, or similar technologies, without the prior written permission of SAE.

TO PLACE A DOCUMENT ORDER: Tel: 1-877-606-7323 (U.S. and Canada only)
Tel: 1-724-776-4970 (outside U.S. and Canada)
Fax: 724-776-0790
Email: CustomerService@sae.org
<http://www.sae.org>

SAE WEB ADDRESS:

Full document details: SAE AS4156D

For more information on this standard, visit
<https://www.sae.org/standards/content/AS4156D/>

**Documents**

Document Sharing Hub

FOREWORD

MIL-DTL-6363H dated 30 September 1997, section 3.7 calls for identification marking. The need for colored insulators to identify parts is no longer needed. Colored insulators can also cause NVIS radiance problems in the cockpit. Any color insulator other than black can diminish visibility, which can put pilots at risk.

1. SCOPE

This document specifies that black is the only color that can be used for the insulator at the bottom of the base of T-1 and T-1 ¾ Flanged Base lamps.

2. REFERENCES

MIL-DTL-6363H dated 30 September 1997, section 3.7.

3. RECOMMENDATIONS

For aerospace applications, lamps are identified by part number. For a full list of part numbers and vendors that are on the Qualified Parts List for T-1 and T-1 ¾ Flanged Base lamps. You can reference MIL-DTL-6363H.

4. NOTES

- 4.1 A change bar (I) located in the left margin is for the convenience of the user in locating areas where technical revisions, not editorial changes, have been made to the previous issue of this document. An (R) symbol to the left of the document title indicates a complete revision of the document, including technical revisions. Change bars and (R) are not used in original publications, nor in documents that contain editorial changes only.

PREPARED BY SAE COMMITTEE A-20, AIRCRAFT LIGHTING

STABILIZED BY SAE A-20A CREW STATION LIGHTING