

SEMI G13-88 (Reapproved 0811) STANDARD TEST METHOD FOR EXPANSION CHARACTERISTICS OF MOLDING COMPOUNDS

This Standard was technically approved by the Assembly & Packaging Global Technical Committee. This edition was approved for publication by the global Audits and Reviews Subcommittee on July 1, 2011. Available at www.semiviews.org and www.semi.org in August 2011; originally published in 1988.

NOTICE: This Document was reapproved with minor editorial changes.

1 Scope

1.1 This Specification describes the procedure for measuring the coefficient of thermal expansion (CTE) and glass transition temperature (T_g) of thermosetting molding compounds.

NOTICE: SEMI Standards and Safety Guidelines do not purport to address all safety issues associated with their use. It is the responsibility of the users of the Documents to establish appropriate safety and health practices, and determine the applicability of regulatory or other limitations prior to use.

2 Referenced Standards and Documents

2.1 *ASTM Standard*¹

ASTM D696 — Coefficient of Linear Thermo Expansion Plastic

NOTICE: Unless otherwise indicated, all documents cited shall be the latest published versions.

3 Apparatus

3.1 *Mold* — Producing 0.1 to 0.2 in. cubes or equivalent with an aspect ratio of 0.8:1.

3.2 *Transfer Press*

3.3 *Micrometer* — 0.0001 accuracy.

3.4 *Thermomechanical Analyzer (TMA)* — Dupont Model 943, Perkin-Elmer TMS-1, or equivalent.

3.5 *Recorder and Power Supply* — Dupont Model 990, Perkin-Elmer UII, or equivalent.

3.6 *Oven* — 200°C ± 5°C capability.

4 Materials

4.1 Nitrogen (Gas).

4.2 Nitrogen (Liquid).

5 Sampling

5.1 Mold samples according to product specifications.

5.2 Posture the specimen in accordance with the material specification, and allow two hours for cooling in a desiccator.

6 Procedure

6.1 Select a sample, making certain that all sides are flat and smooth. Measure the height of the sample with a micrometer to the nearest 0.0001 inch.

6.2 Place the sample into the TMA sample holder and bring the expansion probe down slowly until it just makes contact with the sample. Place sample on fixture per Instruction Manual. Add 3.0 to 5.0 grams to weight tray. Adjust

¹ ASTM International, 100 Barr Harbor Drive, West Conshohocken, PA 19428-2959, USA; Telephone: +1.610.832.9585, Fax: +1.610.832.9555, <http://www.astm.org>

the linear variable differential transformer (LVDT) to bring the recorder pen on scale. The LVDT is then zeroed with the zero switch. Readjust LVDT, if necessary, to bring pen on scale.

6.3 In a nitrogen atmosphere, heat the sample at a rate of 20°C/min. to its post-cure temperature.

6.4 Without changing LVDT or probe position, use liquid nitrogen to cool the sample to a temperature at least 100°C below the deviation from α_1 .

6.5 Heat the sample at a rate of 5°C/min. to at least 200°C.

6.6 Calculate α (CTE), using the formula:

$$CTE = \left[\frac{(DL)(DY)}{(DT)(L)} \right] \quad (1)$$

where: $L_{(T+10^\circ)}$ = Length at Temperature 10° higher than temperature at which CTE is being measured. $L_{(T-10^\circ)}$ = Length at Temperature 10° lower than temperature at which CTE is being measured:

ΔY = Y axis sensitivity in mils./in.

ΔT = change in temperature (20°C)

L = initial sample height (mils)

$K = \frac{LIT \text{ CTE}}{EXP. CTE}$ for aluminum standard

6.7 Run two samples for each lot and record the average.

6.8 An aluminum standard should be run to determine the calibration factor K for the Y (length) axis per 6.4 above, as necessary to insure the accuracy of the instrument's calibration.

6.9 Temperature readings should be calibrated periodically per manual instructions.

7 Report

7.1 Data is to include the orientation for which the sample is measured (e.g., perpendicular to flow).

7.2 CTE is reported as a function of temperature. CTE is to be reported every 10°C increments.

7.3 Report molding conditions and post-mold cure conditions.

7.4 Report specimen size.

NOTE 1: For many materials, the glass transition temperature (T_g) may be determined by drawing tangents to the curve at the points of minimum and maximum slope. The point at which the tangents intersect is the T_g . The slopes of the lines are referred to as α_1 (below T_g) and α_2 (above T_g).

NOTICE: SEMI makes no warranties or representations as to the suitability of the Standards and Safety Guidelines set forth herein for any particular application. The determination of the suitability of the Standard or Safety Guideline is solely the responsibility of the user. Users are cautioned to refer to manufacturer's instructions, product labels, product data sheets, and other relevant literature, respecting any materials or equipment mentioned herein. Standards and Safety Guidelines are subject to change without notice.

By publication of this Standard or Safety Guideline, SEMI takes no position respecting the validity of any patent rights or copyrights asserted in connection with any items mentioned in this Standard or Safety Guideline. Users of this Standard or Safety Guideline are expressly advised that determination of any such patent rights or copyrights and the risk of infringement of such rights are entirely their own responsibility.