

CORRECTION – JUNE 2012

An editorial correction has been incorporated into this version of T 412. A strikeout from the last draft balloted had not been removed, and references in section 6.3 had not been properly numbered as 6.1.1 and 6.2.

**T 412 om-11**

OFFICIAL STANDARD – 1926
 SUGGESTED METHOD – 1969
 OFFICIAL TEST METHOD – 1983
 REVISED – 1990
 REVISED – 1994
 CORRECTED – 1997
 REVISED – 2002
 REVISED – 2006
 REVISED – 2011
 CORRECTED – 2012
 ©2012 TAPPI

The information and data contained in this document were prepared by a technical committee of the Association. The committee and the Association assume no liability or responsibility in connection with the use of such information or data, including but not limited to any liability under patent, copyright, or trade secret laws. The user is responsible for determining that this document is the most recent edition published.

CAUTION:

This Test Method may include safety precautions which are believed to be appropriate at the time of publication of the method. The intent of these is to alert the user of the method to safety issues related to such use. The user is responsible for determining that the safety precautions are complete and are appropriate to their use of the method, and for ensuring that suitable safety practices have not changed since publication of the method. This method may require the use, disposal, or both, of chemicals which may present serious health hazards to humans. Procedures for the handling of such substances are set forth on Material Safety Data Sheets which must be developed by all manufacturers and importers of potentially hazardous chemicals and maintained by all distributors of potentially hazardous chemicals. Prior to the use of this method, the user must determine whether any of the chemicals to be used or disposed of are potentially hazardous and, if so, must follow strictly the procedures specified by both the manufacturer, as well as local, state, and federal authorities for safe use and disposal of these chemicals.

Moisture in pulp, paper and paperboard

1. Scope and significance

1.1 The following procedure applies to pulp, paper, paperboard, and paper products, except those containing significant quantities of materials other than water that are volatile at lower than 107°C (224.6°F) or degrade above 103°C (217.4°F). Moisture is significant for economic reasons and for its effect on such properties as printability, shrinkage, dimensional stability, physical strength, and paper runnability.

1.2 This method should be followed to:

- 1.2.1 Determine the amount of moisture in a lot of pulp, paper or paperboard as an “as received” moisture.
- 1.2.2 Determine the amount of moisture in shipping containers.
- 1.2.3 Calculate results of analysis of the moisture content on the original weight of the specimen.

2. Apparatus

2.1 *Weighing container*, for small specimens, a wide-mouth, glass-stopper weighing bottle approximately 65 mm (2.56 in.) in diameter and 45 mm (1.77 in.) high. For larger specimens, use an airtight metal or other airtight container (non moisture responding), preferably equipped with a removable wire basket, and of such a size as to accommodate the specimens without their being tightly packed. The container used shall be of a material that is not affected by heat.

2.2 *Drying oven*, constant-temperature, with means of ensuring adequate temperature control at $105 \pm 2^\circ\text{C}$ ($221 \pm 3.6^\circ\text{F}$) and free access of air.

NOTE 1: There is danger of local overheating if the specimens are exposed to direct rays of unshielded heating elements.

2.3 *Balance*, accurate to 1 mg (0.000035 oz), for weighing specimens of 2 g (0.000071 oz) and less; for larger specimens, accurate to 0.05% of the original weight of the specimen.

Approved by the Standard Specific Interest Group for this Test Method



Documents

Document Sharing Hub

3. Safety precautions

Employ proper personal protective equipment for removing items from hot ovens.

4. Sampling

4.1 For pulp, sample in accordance with TAPPI T 210 "Sampling and Testing Wood Pulp Shipments for Moisture."

4.2 When sampling a shipment for moisture, take extreme care to avoid any change in the moisture content. For paper and paperboard, sample in accordance with TAPPI T 400 "Sampling and Accepting a Single Lot of Paper, Paperboard, Containerboard, or Related Product."

4.3 For moisture in containers, cut specimens from unsealed and unprinted sections.

5. Test specimens

5.1 For moisture in a lot of pulp, paper or paperboard, obtain duplicate test specimens.

5.2 *General precautions:* Do not use bare hands to handle specimens. Handle specimens and weighing containers with clean, dry, rubber or polyethylene gloves or tools and place each specimen as soon as obtained in the tared container and close it immediately. If there is a delay of even a few seconds in making the transfer, keep the specimen covered on both sides with several of its adjacent layers until it is ready for placement in the container. Unless the specimen is to be spread out later in the oven, avoid filling the container tightly.

6. Procedure

6.1 For large specimens [*larger than 2 g (0.071 oz)*]

6.1.1 Weigh each specimen to the nearest 0.02 g (0.00705 oz) in a closed container. Unless the container has a removable basket, remove the specimen from the container, spread it on a tray preferably made of wire mesh to enable free circulation of air around it and place it and its container in the oven. Heat for 60 ± 5 min at $105^\circ \pm 2^\circ\text{C}$. If grammage is greater than 224 g/m^2 , heat for 120 ± 5 min. If grammage in basis weight is needed to determine the needed time, convert to g/m^2 according to T 410 "Grammage of Paper and Paperboard (Weight per Unit Area)."

6.1.2 Replace the specimen in its container and close it, doing this in the oven if possible. Allow the closed container and contents to cool to room temperature in a desiccator containing a charged drying agent such as anhydrous calcium sulfate. When cool, open the container momentarily to allow air to enter before reweighing and reweigh to the nearest 0.02 g (0.000705 oz).

6.2 For small specimens [*2 g (0.071 oz) or smaller*]

6.2.1 Weigh the specimen in the tared weighing bottle to the nearest milligram, place it in the drying oven, remove the stopper and heat for 30 ± 3 min; for grammages greater than 224 g/m^2 , heat for 60 ± 5 min.

6.2.2 Restopper the bottle, remove it from the oven, cool to room temperature in a desiccator, loosen the stopper momentarily to allow air to enter, and reweigh. Carry out this weighing step within 30 min after removal of the bottle from the oven to prevent reabsorption of water vapor by the specimen.

6.3 For all specimens: after an initial drying period as specified in 6.1.1 and 6.2.1 use a second drying period, at least equal to the first and subsequent drying periods, each of which is at least one-half the total of all previous drying periods, until two successive weighings do not differ by more than 0.1% of the weight of the specimen. During these periods do not put any new test specimens in the oven.

7. Report

Calculate the moisture for each specimen as the percentage loss of the original weight of the specimen, to the nearest 0.1%.

$$\text{Percent moisture content} = \frac{(W_1 - W_2)}{W_1} (100)$$