

SAFETY AND AIRSPACE REGULATION GROUP

ACTIVITY No 2015-00-0088

2 January 2015

See Distribution



AIRSPACE CO-ORDINATION NOTICE

FARNBOROUGH RWY 24 ILS CALIBRATION

ALL TIMES UTC

INTRODUCTION

1. SARG has agreed the following measures with the organiser and airspace controlling authorities to accommodate the subject Unusual Aerial Activity. This ACN replaces ACN 2014-00-0088, which may now be destroyed.

ACTIVITY

2. Calibration of Farnborough ILS Runway 24.

DATES

3. This ACN is valid until further notice.

TIMES

4. The calibration will take place at the following times:
a. As required. Calibration may take up to 4 hours.

VERTICAL LIMITS

5. The following vertical limits apply:
a. Up to 3,000ft above aerodrome level.

CO-ORDINATES OF AREA OR EVENT

6. The calibration will take place in the following area:
a. An arc $\pm 35^\circ$ each side of Runway 24 centreline to 17nm range
b. An arc $\pm 10^\circ$ each side of runway centreline to 25nm range

Civil Aviation Authority

CAA House, K6 G2, 45-59 Kingsway, London, WC2B 6TE. www.caa.co.uk

Tel 0207 453 6599. DFTS (9) 6453 ext 6599. Fax 020 7453 6593.

ausops@caa.co.uk

Page 1 of 5

OPERATING AUTHORITY OR SPONSOR

7. The following authorities will sponsor the calibration:
- a. Cobham Flight Inspection Ltd, Cobham Aviation Services, Bournemouth International Airport, Christchurch, Dorset. BH23 6NE
Tel: 01202 409 111. Mob: 07887 868 568.

CONTROL AUTHORITIES

8. The following agency will provide control for this event:
- a. Farnborough ATC Watch Manager
Tel: 01252 526015.
 - b. LTC (Swanwick) ATC Watch Supervisor,
Tel: 02380 401100.
 - c. Heathrow ATC Watch Manager
Tel: 020 8750 2610.
 - d. Pirbright Range Control
Tel: 01483 798304/ 798474.

AIRCRAFT

9. Beech King Air B200 or DA42 (Diamond).

CO-ORDINATION ARRANGEMENTS

10. **Operating Authority:**
- a. ACN 2015-00-0088 must be quoted in all instances.
 - b. To minimise the effect on Heathrow operations, the sponsor must endeavour to fly the calibration during the period that matches with the runway alternation pattern at Heathrow and avoids the expected times of high "Heavy" departures.
 - c. Five working days before activating this ACN, the sponsor/aircraft captain must contact the following to discuss the implications of forthcoming sorties and agree timings:
 - (1) Farnborough ATC Watch Manager:
Tel: 01252 526015.
 - (2) LTC (Swanwick) ATC Operations Office:
Tel: 01489 612548 / 612292.