

Subject 3992 (444)

April 21, 2017

**TO: Subscribers to UL's Standards Service for
Communications Cables**

Summary of Topics

***This bulletin announces the availability of the Outline of Investigation for Patch Cords
Terminating in Eight-Position Modular Plug Connectors – Performance, UL 3992***

Underwriters Laboratories LLC has issued an Outline of Investigation for Patch Cords Terminating in Eight-Position Modular Plug Connectors – Performance. The outline covers the performance of patch cords utilizing RJ45 style 8-pin modular plug connectors. It also covers the 8-position modular plug connectors used in the construction of these cable assemblies.

Manufacturers interested in submitting equipment for Verification should contact UL's Customer Service at 1-877-854-3577 or e-mail at cec@ul.com.

The UL 3992 Outline is available for purchase from COMM-2000 at 151 Eastern Ave, Bensenville, IL 60106, by phone in the USA and Canada: 1-888-853-3503, by fax in the USA and Canada: 1-888-853-3512, by phone from other countries: INT+1 415-352-2168, by fax from other countries: INT+1 630-932-7387, or from COMM-2000 on-line at <http://www.comm-2000.com>.

UNDERWRITERS LABORATORIES INC.

REVIEWED BY:

ANTHONY TASSONE
Principal Engineer
Wire and Cable
MELVILLE OFFICE
Phone: 631-546-2943
E-mail: Anthony.T.Tassone@ul.com

Copyright © 2017 Underwriters Laboratories Inc.

UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL



Documents

Document Sharing Hub

No Text on This Page

*UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL*



Documents

Document Sharing Hub