

MAY 11, 2018

1

UL 2277

**Outline of Investigation for Flexible Motor Supply Cable and Wind Turbine
Tray Cable**

Issue Number: 4

May 11, 2018

Summary of Topics

This is the Fourth Issue of the Outline of Investigation for Flexible Motor Supply Cable and Wind Turbine Tray Cable. This issue includes requirements for markings in order to meet the new requirements for flexible motor supply cable in the Electrical Standard for Industrial Machinery, NFPA 79.

UL's Outlines of Investigation are copyrighted by UL LLC. Neither a printed nor electronic copy of an Outline of Investigation should be altered in any way. All of UL's Outlines of Investigation and all copyrights, ownerships, and rights regarding those Outlines of Investigation shall remain the sole and exclusive property of UL LLC.

COPYRIGHT © 2018 UL LLC

**UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL**



Documents
Document Sharing Hub

No Text on This Page

*UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL*



Documents

Document Sharing Hub

CONTENTS

INTRODUCTION

1 Scope	4
2 Units of Measurement	4
3 Components	4
4 Undated References	5

CONSTRUCTION

5 Materials and Dimensions	5
6 Assembly	5

PERFORMANCE

7 General	6
-----------------	---

MARKINGS

8 Information on or in the Cable	6
9 Information on the Tag, Reel, or Carton	7

**UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL**



Documents

Document Sharing Hub