

July 30, 2010

1

SUBJECT 4248-18

OUTLINE OF INVESTIGATION

FOR

Fuseholders - Part 18: Photovoltaic

ISSUE NO: 2

July 30, 2010

Summary of Topics

This second issue of the Outline of Investigation for Fuseholders - Part 18: Photovoltaic, Subject 4248-18, is to revise 6.1.1.1 to include marking requirements for fuseholders that include a wire-connector feature, and address non-user replaceable fuses.

COPYRIGHT © 2010 UNDERWRITERS LABORATORIES INC.

UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL



Documents

Document Sharing Hub

No Text on This Page

*UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL*



Documents

Document Sharing Hub