

Guidance Document

G1313

Managing risks from Accessing Signals Assets at height

Issue No.: A1

Issue date: May 2014
Review date: May 2017

Contents

1	Purpose	3
2	Scope	3
3	Guidance	3
3.1	Structural Issues	3
3.2	Access Issues	3
3.3	When an asset is identified with a metal band tag but no red/green tag	4
3.4	When an asset is identified with a red/green tag but no metal band	4
3.5	When an asset is identified with no tags or metal band	4
4	Responsibilities	4
4.1	All Signals Technicians and Managers	4
4.2	Signals Maintenance Managers	4
4.3	Duty Signal Incident Managers	5
4.4	Signal Infrastructure Managers	5
4.5	Signals Discipline Specialist Team	5
4.6	The Civils Team	5
5	Supporting information	5
5.1	Background	5
5.2	Safety considerations	5
5.3	Abbreviations	5
5.4	Person accountable for the document	5
5.5	Document history	5